

1769sc-IF4IH DTM - Changelog.txt
Spectrum Controls 1769sc-IF4IH Device Type Manager
ChangeLog

Author: Jonathan Parmeggiani
Date: 2011-04-04
Version: 1.0.0.4

1769sc-IF4IH DTM

Legend:

- [+] Feature
- [O] No change in behaviour
- [-] Bugfix

1769sc-IF4IH DTM 1.0.0.4

- [-] Fix bug where FieldCare would crash after clicking OK on the configuration dialog

1769sc-IF4IH DTM 1.0.0.3

- [+] Improved tracking of open ActiveX controls.
- [+] Additional tracing if the fame rejects an CloseActiveX request.
- [+] Added support for DrDead hard response.
- [O] Added PrepareToRelease methods to the Channel & ChannelCollection.
- [O] Added connection point interfaces to all COM objects.
- [O] Removed IPersistPropertyBag.
- [O] Added proxy/stub dll to installation package.
- [-] Removed "over RSLinx Backplane" from DTM description.
- [-] IP Address control was not disabled if the user had insufficient security privileges.
- [-] Fixed bug in the DTM's PropagationOfChanges (DTM parameters).

1769sc-IF4IH DTM 1.0.0.2

- [+] HART Pass Through Replies greater than 38 bytes now supported.

1769sc-IF4IH DTM 1.0.0.1

- [+] Added network scanning functionality.
- [+] Moved to Asynchronous communications.
- [+] Modified to work with the AOP of the module.
- [O] Combined CIP messages writing to the Output Image into one packet.

1769sc-IF4IH DTM 1.0.0.0

- [+] Initial Release.